

# **OAKINGTON & WESTWICK PARISH COUNCIL**

## **MEMORIAL MANAGEMENT POLICY**

**ADOPTED 10 JULY 2023**

Any memorial purchased and erected on a grave space is owned by the registered grave owner and it is that person or persons who are ultimately responsible for its upkeep and maintenance.

Historically there have been a number of accidents in cemeteries around the UK, some of which have resulted in fatalities, due to memorials being unsafe. Whilst the memorials are the responsibility of the registered grave owner Oakington & Westwick Parish Council has a responsibility for ensuring that Oakington Cemetery is safe for both staff to work in and for the public to visit.

This Memorial Management Policy sets out the actions the Parish Council will take in order to ensure Oakington Cemetery remains safe.

### **Memorial Fixing**

All memorials over 24.5 inches (625 mm) in height must be fixed to, and fully compliant, with the current British Standard (BS8415). This also extends to ANY memorial over 24.5" (625 mm) that is being re-fixed following an interment or removal for any other reason.

The key requirements are that memorials must be fixed to an approved and suitable foundation (where one is not provided by the Authority) and must be further secured using an approved locking or anchoring system.

Further details on the materials and methods used for fixing and re-fixing of memorials can be found at [www.bramm-uk.org](http://www.bramm-uk.org)

Note that any re-fixing or repair works to memorials must be completed by a BRAMM (or other equivalent scheme) registered memorial mason. Temporary works to make memorials safe and remove the risk of danger will be undertaken by trained Bereavement Services staff.

### **Memorial Inspections**

All memorials over 24" in height in all cemeteries will be inspected by trained staff annually to assess their safety. This will be done through both a visual assessment and a basic hand test to determine if there is movement in the memorial and to what extent.

The individual undertaking the assessment will make the decision on the memorials overall safety based on a dynamic risk assessment for which they have been trained.

Once inspected each memorial will fall into one of three categories, detailed as follows:

**Category Red** – Memorial is unsafe and poses a risk and will require immediate attention to make safe and/or protect from the public.

**Category Yellow**– Memorial is safe but there are minor concerns and it should be reassessed in 12 months' time to ensure it has not deteriorated further.

**Category Green** – Memorial is safe, but will be re-inspected in 1 year as part of the next round of inspections or as part of any other check that may occur, for example when checking memorials around a planned burial ahead of excavation of the grave.

Trained persons undertaking the inspections will record the details of every memorial and an assessment of its safety using the categories above. These details will be recorded in the Parish Council's administration system. The details will include:

- Date of Inspection
- Name of Inspector
- Grave Identification (Section and Number)
- Category of Memorial (Red, Yellow, Green)
- Details of any Actions Taken

### **Actions Post Inspection**

Should a Memorial be identified as a Category Red and fail the inspection staff will need to take immediate action to make that memorial temporarily safe or cordon it off until permanent repairs can be made by the grave owner. These actions will be based on a number of factors and the best solution will be administered by the memorial inspection team based on their assessment of the memorial and the surrounding area. These actions may include:

- **Laying the memorial flat** – In most cases this will invariably be where a memorial can be laid down on or within an existing kerb set so as not to cause a new trip hazard. A warning sign will be placed near to the memorial.
- **Staked and Banded** – The memorial will be fastened tight to a wooden post which will act as a temporary support. The banding will also hold a warning notice. The stake and band will be re-inspected every 12 months to ensure neither have deteriorated.
- **Monolith Conversion** – This involves digging out a depth roughly one third of the overall height of the memorial from the last joint in order that it can be sunk in to the ground and made safe. The memorial will have a suitable material wrapped around the part under the ground and a memorial warning notice will be added to the grave. Due to foundations it may be necessary for the memorial to be moved slightly forward into the grave space to avoid existing foundations.
- **Cordoned Off** – In some cases it may be necessary to cordon off a particular memorial or an area containing a number of memorials due to their safety. Warning signs will be attached to any cordon placed around a memorial or group of memorials.

- **Removal** – In extreme cases it may be necessary to remove a memorial from the grave and place into storage if none of the above options are suitable.

All of the above are regarded as ‘Temporary Fixes’ and should not be seen as a permanent solution to deal with an unsafe memorial and are intended to reduce or remove the risk of a memorial causing harm or damage to someone.

Prior to taking any of the actions above the memorial will be photographed and details recorded of any existing damage or issues.

### **Informing Grave Owners**

Oakington & Westwick Parish Council will endeavour to contact the grave owner where any action has been taken due to a memorial failing a safety inspection. Correspondence will only be sent providing that the grave owner is not recorded as being in the grave or if it is apparent that the registered address no longer exists. For any memorials over 50 years of age no correspondence will be sent but a notice will be left on the grave space for a period of not less than 12 months.

Any memorial that fails an inspection that has been installed within the previous 6 years we will contact the memorial mason directly to request repairs be made to ensure the memorial is fully compliant with BS8415.

### **Grave Owners Responsibilities**

The registered grave owner has a responsibility to ensure the memorial is made safe through being properly re-fixed to the current BS8415 standard and works must be undertaken by a qualified and BRAMM (British Register of Accredited Memorial Masons) registered Memorial Mason. Do it yourself repairs by families will not be permitted.

All costs associated with organising a memorial to be repaired, including the reversal of any works undertaken by Bereavement Services staff, remain the responsibility of the grave owner.

Should grave owners fail to take any action within a reasonable time period Oakington & Westwick Parish Council will look to apply a semi-permanent solution to the memorial, this will involve either laying the memorial flat or sinking the memorial into the ground (monolith conversion).

Laura Lawrence  
Clerk – Oakington & Westwick Parish Council